

# Operations

- ATLAS is in running mode since 12<sup>th</sup> October
  - Beam is scheduled for 23<sup>rd</sup> November
  - Tile gives less trouble than other sub-detectors
- Hardware status
  - LBA22 and LBC47 are off for physics (0.78 %)
  - EBC42 power mis-behaviour (half on, half off)
  - EBC43 has corrupted data
- Calibration sessions twice a day: 9:00 – 11:00 and 17:00 – 19:00
  - CIS ramp for OFV
  - Dedicated runs with different units
- DAQ
  - Stopless recovery in place, not yet “fully” tested
    - When TTC synch was removed, stopless recovery requested removal for all RODs due to a TTC glitch → It works!
  - Issues related to monitoring and Laser ROD being followed
  - Installation area will be locked under the RC supervision as of 13<sup>th</sup> September